

You Missed A QC Seed, Now What?

Harry Wagner, Weston Solutions
Garrick Marcoux, Weston Solutions
Elise Goggin, USACE EM CX



US Army Corps
of Engineers®



Trust. Performance. People.

Committed to Creating a Better Tomorrow

You Missed A Seed, Now What? Making The Most Of Your Quality Program



**“Good decisions come from experience. Experience comes from making bad decisions.”
– Mark Twain**

Trust. Performance. People.

Committed to Creating a Better Tomorrow

Pop Quiz!

- Do we need to seed on transects in a Remedial Investigation?
- What information do you record when you are seeding?
- Does every MQO failure require corrective action?




What Are the Main Failure Modes?


Most seed failures fall into one of these five basic categories :

- Positioning
- Detection
- Targeting
- Classification
- Intrusive

How Do You Find The True Root Cause?



How Do You Find The True Root Cause?



Positioning Failures




**Initial
Corrective Action**

→ Add more targets!


**Additional
Corrective Action**

→ Collect data with IMU to correct for tilt



Detection Failures

- Did you pass the AM and PM IVS tests?
- Do the field notes tell you anything?
- Are there other seeds in the grid?
- Are there other targets in the grid?
- Is the seed too deep?




Engineering, planning, and consulting services for complex environmental and infrastructure challenges




Targeting Failures

- Is your targeting failure actually a positioning or detection failure?
- Did the QC Geophysicist screw up with where they planted the seed? Make a Blind Seed Plan!
- Are there dipole picks at each end of the seed?
- We have started using non-blind seeds in challenging areas and providing the ground truth for these items to the data processor to assist in positioning and targeting TOI.




Classification Failures

- There is a fine balance between paring down the dig list and removing actual TOI.
- Is more automation better to remove the human factor?
- We have seen Cat 3 targets on seeds with nearby Cat 1 targets (but not close enough to meet MQOS).
- Should seeds be placed in cluttered areas?



Engineering, planning, and consulting services for complex environmental and infrastructure challenges



Intrusive Failures

- Set expectations!
- Review data and provide feedback as quickly as possible.
- Can a geophysicist be considered essential personnel and join the initial intrusive effort?



How Do We Explain Failures To Our Clients and Stakeholders?

Communication is key!

- Explain the purpose of QC seeds and set expectations during QAPP development and the TPP process, before there is a failure.
- When you are doing QC and encounter a missed seed, the best thing you can do is respond quickly.
- Let the QA geophysicist know that there is an issue as soon as identified but wait until we have a root cause analysis and corrective action complete to share it with stakeholders.
- At that time, you should be able to answer any concerns they may have and manage expectations.



How Do You Share This Information Across Your Organization?

RCA Tracker

Project	Phase	Failure Mode	Description	QA vs QC	CA	CA Mode	Submitted to USACE	USACE Approval
Former Camp Maxey	Dynamic	Software	AM V5 for Sensor 2 missed positional data and the PM test was collected at 5 Hz instead of the required 10 Hz. The Mesa 3 data logger has been freezing up and during hard reboots system settings are restored.	QC	Retraining of field team on data logger settings so project specific settings can be confirmed.	Retrain	6/21/2022	6/22/2022
Former Camp Maxey	Cued	Human Error	Antenna Height - Data coming out MMX2 is already IMU corrected coordinates. The processing did not account for this.	QC	Applying antenna height of 0 in UK-Analyze to prevent double correction. Reprocessing with this fixed data.	Retrain	6/21/2022	6/22/2022
Former Camp Maxey	Dynamic	Human Error	EM53 System 2 failed the offset MQD in the V5 for both AM and PM tests on May 6, 2022, and System 3 failed the offset MQD in the V5 for the PM test.	QC	The field team was retrained to maintain straight lines when collecting the V5 data. The positioning system must pass directly over the flags that mark the location of the V5 items.	Retrain	10/24/2022	11/17/2022
Former Camp Maxey	Dynamic	Software	The EM53 was set to 5Hz instead of 10Hz. 2 days of data needed to be re-collected at the appropriate setting.	QC	Retraining of the field crew in appropriate settings and procedures for verifying them.	Retrain	10/24/2022	11/17/2022
Former Camp Maxey	Settling	Hardware	QC seed not set with 50cm MQD because the ground truth was off by 80cm. During QC seeding the RTK GPS had lost communication with the base station.	QC	QC Geophysicist will ensure that the operator has RTK fix when shooting in seed coordinates.	Retrain	9/22/2022	11/17/2022
Former Camp Maxey	Static	Process	Evaluation of background decay plots revealed the background used to level the dataset including the QC seed was strange compared to the other data recorded at that big location.	QC	Recollect cued data that used that big shot to level the data. Evaluate all big decay plots for this issue elsewhere. Update SOP	SOP	10/26/2022	11/9/2022
Former Camp Maxey	Dynamic	Process	Blind QC seed in grid A12 (Whisenhunt property) was detected, however picks were placed at each end of the east-west seed and neither target was within the 50 cm MQD for horizontal offset. It has been general practice to manually select targets located between isolated pairs of peaks. The data analyst neglected this additional target selection for the Whisenhunt property.	QC	The Whisenhunt data were reexamined. 37 additional targets were added between isolated pairs of peaks. The data analyst was reminded to do so each time for future properties.	Retrain	12/21/2022	12/22/2022
Former Camp Maxey	Static	Human Error	Blind QC seed in grid A14 (Whisenhunt property) was detected, however the anomaly and corresponding target were offset to the southwest and outside of the 50 cm MQD for horizontal offset.	QC	Dataset containing failed seed collected on 10/17 with RTK was re-collected with RTK. Control points established for the RTK had errors in the methods used during establishment. The field crew was retrained to prevent future errors.	Retrain	12/21/2022	12/22/2022
Mount Owen RI	Intrusive	Process	26 targets in the burn area were measured over the 25cm MQD from their predicted locations.	QC	Review of the MQDs and SOPs with retraining for RTK systems. Reinforce importance of multiple measurements for multiple sources.	Retrain	6/30/2022	7/1/2022
Mount Owen RI	Intrusive	Process	Blind seed was properly classified but not recovered during intrusive activities.	QC	The dig team will be re-briefed on MR-SOP-5 and will check the excavation with analog instruments prior to backfilling. UROQC will conduct their inspection the same day of target excavation and if this is not possible, the subject target positions will be re-taken with RTK prior to the QC inspection. The intrusive results were reviewed for source results determined not to be a qualitative match to predicted TO and where the final excavation depth did not meet or exceed the depth prediction or there was uncertainty associated with the final depth. The team will return to the following target positions to re-dig to 15 centimeters beyond the predicted depth and check for additional sources with available instruments: 1.13, 1.19, 1.50, 1.43, 1.44, and 1.45.	Retrain	10/17/2022	12/19/2022

Lesson Learned Portal

Event Title	Date Occurred	Event Description	Recommendations	Preventive Actions	Category	Key words
SLAM Batteries	12/28/2022	Kaiseros 50,000mah batteries provided with stencil die rapidly, are not rugged enough for long term use and do not allow for hot swap capability.	Switched to Ind Pro 270Wh V-mount style batteries. These have lasted 5-6 hours (compared to 0.5-3 hrs for previous style battery), have a charger that cuts power to prevent overcharging, are much more rugged/durable and allow for battery hotswaps.	Purchases required Ind Pro V-mount style batteries prior to field work.	Other	SLAM, Stencil, Battery, Batteries, V-Mount, Krisdona, power, hot swap, charging, Ind Pro
Processing Dynamic MetalMapper 262 Data	11/18/2022	When processing dynamic MMX2s data, there is a bug in the software (Version 2022.1) that causes the latency connection applied to the mono in the located database to be lost when running the "Determine CAT" tool. If the tool is ran a second time, for any reason, the latency connection will be lost. The main reason we tend to re-run the tool is due to an error in which the background amplitude threshold is too low. The error message reads "The maximum number of attempt (100) was reached when trying to find a location that is below the background threshold of (inputted threshold value). The lowest data value found was X. Adjust your background threshold. Consider an alternate TO and/or project depth. Review your Data Processing and Background Removal/leveling parameters."	From Sequence: If you do have to run the tool again, for this reason for example, please run the "Create Located database" again first. This will reset the Monostatic channel back to what it should be. Then when you run the Determine CAT tool, your amp anomaly grid should have the latency applied.	Anytime you re-run your determine CAT tool, make sure you re-created your located database. Also from Sequence: The second time you run the CAT tool only affects the Located database (it alters the Monostatic channel), not the Data database. That is why if you do run the determine CAT tool again, you only need to recreate the Located database. (2) you can see how the monostatic channel gets altered in the Located database by displaying a breakout channel from the monostatic array; create a new channel called Monostatic[S] - this will populate a channel with the 5th gate of the monostatic array - which you will see is different (after you run determine CAT), then the Monostatic-S channel.	Other	Dynamic, MetalMapper262, MMX2s, latency, Determine CAT
SLAM Mounting Adapter	11/1/2022	The warning indicates that no values in your grid are below background for the given TO and depth. The 1/4-20 threading on the stencil mounting adapter drilled through the base of the stencil and punctured the electronics causing the equipment to malfunction.	Mounting adapters for stencil will have different lengths of exposed threading. Operators need to assure a spacer is being used if the length of exposed threading exceeds the thickness of the mounting plate (1/4 in thickness). Fender washers can be used to take up any excess space.	Always measure your exposed threading and determine if you need a spacer prior to installing the mounting adapter. This should be done initially and every time a mounting adapter needs to be replaced.	Other	SLAM, mounting adapter, threading, washer, spacer
HDFS File Import Error - Oasis (Montaj) Version 2022.1 (20220602.26)	7/8/2022	When attempting to import any HDF files (dynamic or static), an error was received stating "table object must have a value". Not allowing any import of HDF files into Oasis.	The solution was to remove any manually input underscores in your database naming conventions. For example "BCC_3350mm4b_SAM_Targer" must be changed to "BCC3350mm4b_SAM_Targer". This was not an issue in previous Oasis versions. This is what Sequence had to say about it. "Although we don't spring an error or have validation for users using an underscore in their database prefixes, we do strongly discourage it. A lot of overkeys	Avoid using any underscores in your naming convention of databases in Oasis Montaj version 2022.1 (20220602.26).	Other	Oasis (Montaj) Version 2022.1 (20220602.26) HDF Import



Engineering, planning, and consulting services for complex environmental and infrastructure challenges



Questions?



Remember, failures are opportunities to learn. They aren't a bad thing unless you keep making the same mistakes over and over.



Want To Know More?

Contact Us

Harry Wagner, CQM

MMRP Geophysical QC Manager
Weston Solutions, Inc.

 Harry.Wagner@WestonSolutions.com

 775-225-1424

Garrick Marcoux, PGp

MMRP Geophysical Group Manager
Weston Solutions, Inc.

 Garrick.Marcoux@WestonSolutions.com

 865-566-1013

Elise Goggin

QA Geophysicist
USACE EM CX

 Elise.M.Goggin@usace.army.mil

 256-640-5822

Trust. Performance. People.

